

Er. Pramod Kumar

B.Sc. (Engg) Civil F.I.V. (Delhi) No. F-16120,

M.I.E. (India), M-1394835

Corporate Valuer, Designer, Planner

Valuer, LIC HFL

Approved Civil Engineer, UDHD, Govt. of Bihar

Regd. No. BR/UDHD/CE/23-0346

Approved Structural Engineer, UDHD, Govt. of Bihar

Regd. No. BR/UDHD/SE/25-0253



LIC Colony, Bahadurpur,

Zero Mile, Sabour Road

Bhagalpur - 813210

Mb. No.- 7903537597

BUILDING SAFETY CERTIFICATE

This is to certify that I have inspected the school building of Delhi Public School (DPS) situated at Deekshapuram, Sabour, Bhagalpur (Bihar) – 813210.

1. Details of the Building:

Secondary School – 3000 sq.m

Sr. Secondary School (with two streams) – 2000 sq.m

Total Built-up Area: 5000 sq.m

Date of Inspection: 31.03.2026

School Building is G+3 Storied RCC Structure

2. Certificate:

On the basis of visual inspection of the building and available information, it is certified that the above school building is structurally safe and fit for the intended educational purpose.

3. Validity:

This certificate is valid subject to proper maintenance and no structural distress.

4. Remarks (if any):

The above described school building (DPS) has complied with the Building Safety Requirements accordance with National Building Code Rules and that the building / premises is fit for occupancy up to classes XII.

Issued on 01.04.2026 at Bhagalpur:

Place: Bhagalpur

Date: 01.04.2026

Pramod Kumar
01.04.2026

(Signature of Structural Engineer)

Pramod Kumar

Regd. Structural Engineer,

UDHD, Govt. of Bihar.

Regd. No.: BR/UDHD/SE/25-0253

Er. Pramod Kumar
Approved Structural Engineer
Regd.No.-BR/UDHD/SE/25-0253
Govt. of Bihar